## SZUTEST

## **CERTIFICATE OF CONFORMITY**

Project No: SZU-1931802

Date of First Issue of Licence: 01/01/2020

Licence Valid Until: 14/11/2022

Name of Licence Holder: Fikret Yıldırım Amt İleri Metal Teknolojileri

Address of Licence Holder: İnönü Mh. Cenk Cd. İkizler Sk. No:3-5 Daire :7 Sefaköy /

K.Çekmece / İstanbul

Manufacturer: Fikret Yıldırım Amt İleri Metal Teknolojileri

Manufacturing Address: İnönü Mah. Cenk Cad. İkizler Sokak No:5 -7 Sefaköy / K.

Çekmece – İstanbul

Product: Pipe Clamps With Combi Nut-Lined

Type: Pipe Hangers

Qualification Range: (1/4" to 8")

Manufacturing Year: 2019

Related Test: Tensile Test(See appendix-1 for test result)

Related Report : See appendix

**Test / Inspection Date:** 11.11.2019-13.11.2019

Test / Inspection Place: Ataşehir – İstanbul / TURKEY

Test Result: Convenience in accordance with Company's Catalogues

Tensile tests were performed with calibrated tensile test machine, with serial number 584-CET-01 on pipe clamp with combi nut-lined types with the sizes 1/4", 3/8", 1/2", 3/4", 1",11/4", 11/2", 53-59 mm, 2", 67-77 mm, 21/2", 83-93 mm, 3", 94-104 mm, 102-111 mm, 4", 122-135 mm, 128-139 mm, 5", 151-164 mm, 6", 194-205 mm and 8" manufactered by Mega Baglanti ve Tesbit Elemanları and it was observed that the test results meet the required minimum load values at fracture mentioned in the catalogues of Mega Baglanti ve Tesbit Elemanları

This certificate was issued upon the request of the company.

These tests are performed by accredited laboratory.

Head of Industrial Services Department

SZU.		S		TENSÎLE TEST REPORT		Date: 13.11.2019 Page:
ТУРЕ	SIZE	CLAMPING RANGE	SAMPLE NO	LOAD VALUE AT FRACTURE MENTIONED IN THE CATALOGUE( kN )	LOAD VALUE AT FRACTURE OBSERVED BY THE TEST( kN )	DEFORMATION TYPE
PIPE CLAMP WITH COMBI NUT - LINED	1/4"	13-20 mm	SAMPLE 1		5,476	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1/4"	13-20 mm	SAMPLE 2	3,9 kN	5,068	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1/4"	13-20 mm	SAMPLE 3		5,619	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3/8"	17-23 mm	SAMPLE 1	3,9 kN 3,9 kN 3,9 kN	5,266	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3/8"	17-23 mm	SAMPLE 2		5,603	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3/8"	17-23 mm	SAMPLE 3		5,29	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1/2"	21-26 mm	SAMPLE 1		5,564	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1/2"	21-26 mm	SAMPLE 2		5,421	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1/2"	21-26 mm	SAMPLE 3		4,893	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3/4"	26-30 mm	SAMPLE 1		5,337	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3/4"	26-30 mm	SAMPLE 2		6,325	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3/4"	26-30 mm	SAMPLE 3		5,164	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1"	33-37 mm	SAMPLE 1	3,9 kN	5,364	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1"	33-37 mm	SAMPLE 2		5,04	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1"	33-37 mm	SAMPLE 3		5,634	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1 1/4"	40-46 mm	SAMPLE 1	4,8 kN	5,917	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1 1/4"	40-46 mm	SAMPLE 2		5,783	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1 1/4"	40-46 mm	SAMPLE 3		6,732	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	1 1/2"	48-53 mm	SAMPLE 1	4,8 kN	5,157	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED PIPE CLAMP WITH COMBI NUT - LINED	1 1/2"	48-53 mm 48-53 mm	SAMPLE 2 SAMPLE 3		6,598	Side screw was clamped off
	53-59		SAMPLE 1		6,793	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED PIPE CLAMP WITH COMBI NUT - LINED	53-59	53-59 mm 53-59 mm	SAMPLE 2	4,8 kN 4,8 kN	10,853	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	53-59	53-59 mm	SAMPLE 3		5,517 5,206	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	2"	60-66 mm	SAMPLE 1		7,631	Side screw was clamped off
PIPE CLAMP WITH COMBINOT - LINED	2"	60-66 mm	SAMPLE 2		5,884	Side screw was clamped off Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	2"	60-66 mm	SAMPLE 3		7,769	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	67-77	67-77 mm	SAMPLE 1		7,921	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	67-77	67-77 mm	SAMPLE 2	4,8 kN	6,83	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	67-77	67-77 mm	SAMPLE 3		7,618	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	2 1/2"	75-84 mm	SAMPLE 1	6,9 kN	12,659	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	2 1/2"	75-84 mm	SAMPLE 2		12,11	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	2 1/2"	75-84 mm	SAMPLE 3		12,232	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	83-93	83-93 mm	SAMPLE 1	6,9 kN	7,045	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	83-93	83-93 mm	SAMPLE 2		8,041	Combi nut threat clamped off
PIPE CLAMP WITH COMBI NUT - LINED	83-93	83-93 mm	SAMPLE 3		11,25	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3"	87-96 mm	SAMPLE 1	6,9 kN	11,166	Combi nut was broken from welding
PIPE CLAMP WITH COMBI NUT - LINED	3"	87-96 mm	SAMPLE 2		7,293	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	3"	87-96 mm	SAMPLE 3		11,331	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	94-104	94-104 mm	SAMPLE 1	6,9 kN	7,155	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	94-104	94-104 mm	SAMPLE 2		8,334	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	94-104	94-104 mm	SAMPLE 3		7,916	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	102-111	102-111 mm	SAMPLE 1	6,9 kN	8,757	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	102-111	102-111 mm	SAMPLE 2		6,925	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	102-111	102-111 mm	SAMPLE 3		8,624	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	4"	109-119 mm	SAMPLE 1	6,9 kN	11,385	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	4"	109-119 mm	SAMPLE 2		7,587	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	4"	109-119 mm	SAMPLE 3		10,284	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	122-135	122-135 mm	SAMPLE 1	6,9 kN	11,503	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	122-135	122-135 mm	SAMPLE 2		10,853	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	122-135	122-135 mm	SAMPLE 3		10,595	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	128-139	128-139 mm	SAMPLE 1	6,9 kN	7,904	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	128-139	128-139 mm	SAMPLE 2		8,355	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	128-139	128-139 mm	SAMPLE 3		7,653	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	5"	135-148 mm	SAMPLE 1	7,8 kN	7,601	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	5"	135-148 mm	SAMPLE 2		10,365	Combi nut was broken from welding
PIPE CLAMP WITH COMBI NUT - LINED	5"	135-148 mm	SAMPLE 3		11,243	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	151-164	151-164 mm	SAMPLE 1	7,8 kN	11,271	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	151-164	151-164 mm	SAMPLE 2		10,524	Side screw was broken
IPE CLAMP WITH COMBI NUT - LINED	151-164	151-164 mm	SAMPLE 3		10,95	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	6"	158-170 mm	SAMPLE 1	7.0 (A)	8,712	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED	6" 6"	158-170 mm	SAMPLE 2	7,8 kN	7,789	Side screw was clamped off
	n l	158-170 mm	SAMPLE 3		10,577	Side screw was clamped off
PIPE CLAMP WITH COMBI NUT - LINED					2 255	Contraction of the Contraction o
IPE CLAMP WITH COMBI NUT - LINED  IPE CLAMP WITH COMBI NUT - LINED  IPE CLAMP WITH COMBI NUT - LINED	194-205 194-205	194-205 mm 194-205 mm	SAMPLE 1	7,8 kN	9,057 9,729	Side screw was broken Side screw was broken

PIPE CLAMP WITH COMBI NUT - LINED	8"	214-224 mm	SAMPLE 1		9,705	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	8"	214-224 mm	SAMPLE 2	7,8 kN	8,369	Side screw was broken
PIPE CLAMP WITH COMBI NUT - LINED	8"	214-224 mm	SAMPLE 3		9,869	Side screw was clamped off
Approved by:			11		***************************************	***************************************
Date:			1 /// -			
Signature:			4/11/			
			11/11			